



Advantech Manufacturing, Inc

2450 S. Commerce Drive
New Berlin, WI 53151

Toll Free: 800.511.2096
Tel: 262.786.1600
Fax: 262.786.5074

www.advantechmfg.com
sales@advantechmfg.com

Sieve Certification, Inspection or
Calibration Schedule *

Periodic Certification, Inspection or Calibration of test sieves is recommended as with any other precision laboratory instruments. Generally, the finer woven wire cloth requires more frequent inspections. The proper use and handling of each sieve is paramount to the long-term accuracy of your sieve. Re-Certification, Re-Inspection or Re-Calibration greatly depends upon your media, frequency of usage, sieve handling and care, and your internal quality system requirements.

The table below offers a basic guideline for scheduling your sieve re-certification, re-inspection or re-calibration.

Sieve Aperture	Number of Uses		Months in Use
5" to ¼"	80	or	36
½" to No. 12	70		30
No. 14 to No. 40	60		24
No. 45 to No. 140	50		18
No. 170 to No. 325	35		12
No. 400 to No. 635	20		6

If you are interested in having your Test Sieves Certified, Inspected or Calibrated, please contact us at **800.511.2096** or email **sales@advantechmfg.com**.

- Sieve Certification, Inspection or Calibration is performed on the purchase of a new sieve.
- Sieve Re-Certification, Re-Inspection or Re-Calibration is performed on your existing sieve.

**For more detailed information on Sieve Compliance, Inspection and Calibration requirements, please refer to the ASTM E 11-09 Standard Specifications for Woven Wire Test Sieve Cloth and Test Sieves.*